

### Catalogue

Warning	2
I . Brief Introduction	4
II . Electrical Symbols	5
III. Series Model	5
IV. Technical Specification	6
V. Structure	8
VI. LCD Display	9
1. LCD Display Screen	9
2. Explanation for Special Symbols	9
3. Display Demonstration	10
₩. Operation Ways	11
A. Tester Operation	11
1. Power On/Off	11
2. General Test	12
3. PEAK Test	13
4. Data Maintenance	14
5. Data Memory	14
6. Data Reference	14
7. Data Deletion	14
8. Data Transmission	15
B. Operation of Receiver	15
1. Power On/Off	15
2. Data Reception	15
3. Data Maintenance	16

4. Data Memory	16
5. Data Reference	16
6. Data Deletion	16
Ⅷ. Replacing Batteries	17
IX. Packing List	18



Thanks for your purchase of **VICTOR9000 H/L Voltage Clamp Meter** of our company. In order to make better use of this product, please make sure to:

——Read this manual in detail and the operator must totally understand this manual and be in proficient in operation of this meter before making test on spot.

# ——Strictly comply with the security rules and notice items listed on this manual.

- In any case, it should pay special attention to safety in use of this meter, particularly in measurement of circuitry with more than AC100V and above voltages.
- If the voltage of tested circuitry has exceeded 600V, it must be used by connecting with an insulation rod.
- As it is very dangerous of high voltage transmission line, the operator must get strict training and the relevant certification on high-pressure operation of the state before using this meter and making a field test.
- It is strictly forbidden to use this meter to test the wire or convergence generatrix without any insulation.
- Please pay attention to marked words and symbols on panel or backboard of this meter.
- Please do not put or store this meter in the place of high temperature, with moisture, with frozen dew or with direct

daylight irradiation for a long time.

- Please note the battery polarity when replacing battery, and remove the battery if do not use this meter for a long time.
- It must be operated by qualified staff that has the authorization on tearing down or repairing this meter.
- Please do not use it when there is any damage on the transducer clamp or other parts of this meter.
- To avoid the impact of transducer clamp, it needs to maintain this meter regularly. Do not use corrosive or coarse articles to clean, but use soft cloth (such as glasses cloth), dipping clean anti-rust desiccant lubricant (such as WD-40), and making a gentle wiping.
- For the reason of this meter, in case that any danger may occur if continue to use it, stop using it immediately and seal it up for keeping at once, which shall be dealt with by qualified authorization agency.
- The danger symbol " monoperation according to the indication.
- The extremely dangerous symbol " ]", the user must make safe operation according to the indication.
- It suggests that this meter shall be made insulation intensity test at least once annually. (AC 40kV/rms between insulation pole and clamp core.)
- As to the part with "\*"mark in this manual, it is only limited to VICTOR9000B type (wireless Transmission data type).

### I. Brief Introduction

VICTOR9000 Series H/L Voltage Clamp Meter has broken through the traditional structure, which is specially well-designed for measuring high voltage current, adopting the latest CT technology and integrated mask digital technology, formed by composition of a special use clamp meter with a high-voltage VICTOR9000B insulation rod as to tvpe --wireless transmission of test data, it is equipped with wireless receivers, which can be received inside the 30-meter line measured data. If not using an insulation rod, it can be also used as a high precision low-voltage clamp meter, or an alternating current meter, which can accurately measure0.1mA of current or leakage current.

**VICTOR9000** Series **H/L Voltage Clamp Meter** has an innovative integrated design between transducer clamp and transducer domain, ensuring the high-precision, high-reliability, and high-stability on constant test perennially.

VICTOR9000 Series H/L Voltage Clamp Meter is connected with insulation rod, which can be used for measuring high voltage current that is below 23KV, on-line current measurement, also having peak maintenance, data preservation, data storage, wireless transmission and other functions, and its special clamp meter can make it easier for clamping or evacuating the tested wire through pressing or pulling back the insulation rod, time-saving and fast, widely used in transformer substation, power plant, industrial and mining enterprises as well as the inspection station and electrician maintenance departments for electrical current detection and field electrical operations. It can also replace the H/L voltage transforming ratio tester, that is, to detect the high and low current for primary circuit and secondary circuit separately, and then calculate to conclude the change of high and low pressure. The insulation rod is light and convenient, with the advantages of anti-moisture, high temperature resistance, anti-impact, bending resistance, high insulation, flexibility and other characteristics.

### **II. Electrical Symbols**

5	Extremely Dangerous! The operator must strictly abide by the safety rules. Otherwise, there is electric injury danger, causing personal damage or casualty accident.
A	Dangerous! The operator must strictly abide by the safety rules. Otherwise, there is electric injury danger, causing personal damage or casualty accident.
	Warning! It must strictly abide by the safety rules. Otherwise, it may cause personal damage or casualty accident.
$\sim$	Alternating Current (AC)
	Direct Current (DC)

### ${\rm III}.\,$ Series Model

Model	Range of measurement	Accuracy	Jaw Specification	Description
VICROR	0.1mA-1000A	0.1mA	φ48mm	base
9000				
VICTOR	0.1mA-1000A	0.1mA	φ48mm	Wireless
9000B				

### $\ensuremath{\mathrm{IV}}\xspace$ . Technical Specification

Function	High voltage AC current measurement, low voltage AC current, leakage current measurement, on-line AC current supervision.	
Power Supply	DC6V Alkaline Dry Battery (1.5V AAA X 4)	
Test Method	Clamp CT, Integral Method	
*Transmission Method	B Model: Wireless Transmission, the maximum distance for direct transmission is about 30m.	
Display Mode	4 digital LCD display, backlight function, suitable for dark place.	
LCD Dimension	47mm×28.5mm	
Meter Dimension	W/H/T: 76mm×255mm×31mm	
Clamp Diameter	φ <b>48mm</b>	
Sampling Speed	About 2 times/second	
Range of measurement	0.1mA~1000A(50/60Hz Auto Identification)	
Accuracy	0.1mA	
Shift	0.1mA~1000A Automatic Shift	
	0.1mA $\sim$ 299mA: $\pm$ 1% $\pm$ 3dgt	
Test Accuracy	0.30A~49.9A: ±1.5%±5dgt	
(23℃±5℃, Below 80%RH)	50.0A~199.9A: ±2.0%±5dgt	
	200A~600A: ±3%±5dgt	
	601A $\sim$ 1000A: ±4%±5dgt	
Data Storage	99 Groups, during storage, the symbol "MEM" gives indication, "FULL" mark will flash to indicate the memory has been full.	
Circuit Voltage	Test for the circuit below 23KV (operated with insulation rod)	


Peak Maintenancevalue, usually in the test mode pressPEAK key, PEAK lights, that is, to keep open the PEAK function, then pressData PreservationUnder general test mode, pressHOLD button to preserve data, "HOLD" symbol display. then pressData Access"MR" symbol indicates, it can read the stored data by turning upwards and downwards.Overflow DisplayExceed measurement range overflow function: "OL A" symbol displayAuto Shut DownAbout 15 minutes after booting, the meter will shut down automatically, in order to decrease the battery consumption.Meter QualityWhen the battery voltage is below 4.8V, the symbol of battery.Work Temperature and Humidity-10°C~40°C; Below 80%RhStorage Temperature and Humidity-10°C~60°C; Below 70%RhInsulated Rod Dimension\$ 32mm, 1m/Section (5 Sections)			
Datato preserve data, "HOLD" symbol display. then press HOLD Key to cancel this functionData Access"MR" symbol indicates, it can read the stored data by turning upwards and downwards.Overflow DisplayExceed measurement range overflow function: "OL A" symbol display* No signal IndicationWhen the receiver has not received transmit signal, it will display "no" symbolAuto Shut DownAbout 15 minutes after booting, the meter will shut down automatically, in order to decrease the battery consumption.Battery VoltageWhen the battery voltage is below 4.8V, the symbol of battery voltage" = * "will show to remind to replace battery.Weter QualityTester: About 335g (Including battery), total quality of meter: about 2.5Kg (including insulation rod and battery.)Work Temperature and Humidity-10°C~40°C; Below 70%RhInsulated Rod Dimension\$ 32mm, 1m/Section (5 Sections)	, out	key, PEAK lights, that is, to keep open the PEAK function, then press <b>PEAK</b> key to cancel this function	
Data Access"MR" symbol indicates, it can read the stored data by turning upwards and downwards.Overflow DisplayExceed measurement range overflow function: "OL A" symbol display* No signal IndicationWhen the receiver has not received transmit signal, it will display "no" symbolAuto Shut DownAbout 15 minutes after booting, the meter will shut down automatically, in order to decrease 		to preserve data, "HOLD" symbol display. then	
Data Accessdata by turning upwards and downwards.Overflow DisplayExceed measurement range overflow function: "OL A" symbol display* No signal IndicationWhen the receiver has not received transmit signal, it will display "no" symbolAuto Shut DownAbout 15 minutes after booting, the meter will shut down automatically, in order to decrease the battery consumption.Battery VoltageWhen the battery voltage is below 4.8V, the symbol of meter: about 2.5Kg (including insulation rod and battery.)Work Temperature and Humidity-10°C~40°C; Below 80%RhStorage Temperature and Humidity-10°C~60°C; Below 70%RhInsulated Rod Dimension\$ 32mm, 1m/Section (5 Sections)		press <b>HOLD</b> Key to cancel this function	
Display"OL A" symbol display* No signal IndicationWhen the receiver has not received transmit signal, it will display "no" symbolAuto Shut DownAbout 15 minutes after booting, the meter will shut down automatically, in order to decrease the battery consumption.Battery VoltageWhen the battery voltage is below 4.8V, the symbol of battery voltage" □+1 "will show to remind to replace battery.Meter QualityTester: About 335g (Including battery), total quality of meter: about 2.5Kg (including insulation rod and battery.)Work Temperature and Humidity-10°C~40°C : Below 80%RhStorage Temperature and Humidity-10°C~60°C : Below 70%RhInsulated Rod Dimension\$ 32mm, 1m/Section (5 Sections)	Data Access	-	
Indicationsignal, it will display "no" symbolAuto Shut DownAbout 15 minutes after booting, the meter will shut down automatically, in order to decrease the battery consumption.Battery VoltageWhen the battery voltage is below 4.8V, the symbol of battery voltage" → "will show to remind to replace battery.Meter QualityTester: About 335g (Including battery), total quality of meter: about 2.5Kg (including insulation rod and battery.)Work Temperature and Humidity-10°C~40°C; Below 80%RhStorage Temperature and Humidity-10°C~60°C; Below 70%RhInsulated Rod Dimension\$ 32mm, 1m/Section (5 Sections)	••••••	"OL A" symbol display	
Auto shut Downshut down automatically, in order to decrease the battery consumption.Battery VoltageWhen the battery voltage is below 4.8V, the symbol of battery voltage" I "will show to remind to replace battery.Meter QualityTester: About 335g (Including battery), total quality of meter: about 2.5Kg (including insulation rod and battery.)Work Temperature and Humidity-10°C~40°C; Below 80%RhStorage Temperature and Humidity-10°C~60°C; Below 70%RhInsulated Rod Dimension\$ 32mm, 1m/Section (5 Sections)		signal, it will display " <b>no</b> " symbol	
Battery Voltagesymbol of battery voltage" → "will show to remind to replace battery.Meter QualityTester: About 335g (Including battery), total quality of meter: about 2.5Kg (including insulation rod and battery.)Work Temperature and Humidity-10°C~40°C; Below 80%RhStorage Temperature and Humidity-10°C~60°C; Below 70%RhInsulated Rod Dimension\$ 432mm, 1m/Section (5 Sections)		shut down automatically, in order to decrease	
Meter Qualityquality of meter: about 2.5Kg (including insulation rod and battery.)Work Temperature and Humidity-10°C~40°C; Below 80%RhStorage Temperature and Humidity-10°C~60°C; Below 70%RhInsulated Rod Dimension\$ 32mm, 1m/Section (5 Sections)	Battery Voltage	symbol of battery voltage" =+ "will show to	
Temperature and Humidity-10℃~40℃; Below 80%RhStorage Temperature and Humidity-10℃~60℃; Below 70%RhInsulated Rod Dimensionφ 32mm, 1m/Section (5 Sections)	Meter Quality	quality of meter: about 2.5Kg (including	
Temperature and Humidity $-10^{\circ}C \sim 60^{\circ}C$ ; Below 70%RhInsulated Rod Dimension $\phi$ 32mm, 1m/Section (5 Sections)	Temperature	-10℃~40℃, Below 80%Rh	
Dimension (5 Sections)	Temperature	-10℃~60℃, Below 70%Rh	
Insulation AC 40KV/rms (Retween insulation rod and			
Intension clamp core)	Insulation Intension	AC 40KV/rms (Between insulation rod and clamp core)	
Structure Anti-Dripping Type II	Structure	Anti-Dripping Type II	

### V. Structure

- 1. Clamp head (including the boot area)
- 2. VICTOR9000 Tester
- 3. LCD Display
- 5. PEAK Key
- 7. HOLD Key
- **9.** Insulation Rod Connector

\*11.VICTOR9000B Testers

- 4. PEAK Test Indication
- 6. POWER Key
- **\*8.** VICTOR9000B Receiver **\*10**.POWER Indication



VICTOR9000

VICTOR9000B

### VI. LCD Display

#### 1. LCD Display Screen


- $(1). \ \textbf{AC Symbol}$
- (2). Symbol of low

Batteries & Voltage

- (3). Date storage symbol
- (4). Date access symbol
- (5). 2-digit Storage Data Serial Number
- (6). Unit Symbol
- (7). Date Locked Symbol
- (8). Decimal System Radix Point
- (9). 4-Digit LCD Digital Display

#### 2. Explanation for Special Symbols

- Symbol of Battery & Voltage, when Battery & Voltage is lower than 4.8V, this symbol display, please replace battery in time.
- (2)."OL A" This symbol denotes that the current on test has exceeded the maximum measurement limit of the meter.
- (3)."**MEM**" Memory Mode, it will show during the storage process of the data.
- (4). "Full" Symbol, when the storage data has been filled with 99 groups, it will show "FULL" symbol by flash, which means it cannot continue to store data.
- (5). **MR** data access symbol, which is shown during referring to data, meanwhile, it will show the serial number of data in



storage.

- (6)."End" exit symbol, it will show during sign out.
- (7)."dEL" data delete symbol, it will show during deleting.
- \*(8)."**no-** -" None received signal instructions, dynamic display, it may not in test mode, or adjust the location and distance from receiver.

#### 3. Display Demonstration

- (1). ——The current on test is 0.002A(2mA)
- (2). ——Locked display Data
  - ——The data is automatic stored as group 3
  - ——The current on test is: 160.5A
- (3).—The current on test is: 571A
  —Low Battery & Voltage symbol display, please replacing.
- (4).——Refer to data of group 3 in storage
  - -----The current on test is: 160.5A
- (5).—— "FULL" flash display:
  - Storage is full of 99 groups
  - ——It can't store more unless delete storage
- (6).----"dEL" Indication of data delete
- (7).----- "End" Indication of Exit
- \*(8).——"no- -"Dynamic display: none received signal



### VII. Operation Ways

Please check all parts of the meter carefully before usage, to see whether there is any damage. And make sure no damage before usage.

According to manual instructions to install the battery

#### A. Tester Operation

#### 1. Power On/Off

ſ

Press **POWER** button for power on, LCD display, entering normal test mode. If LCD display is relatively dark after power on, it is possible that battery voltage is a bit lower. Please replace battery. In 15 minutes after power on of the meter, LCD will continue flashing to give hint for automatic power off, after 30 minutes for continuous flash of LCD, it will shut down automatically, in order to lower the battery consumption. In case of LCD continuous flash, press **POWER** button, then the meter will continue to work.

Under HOLD mode, press **POWER** button for power off. Under general test mode, press **POWER** button for power off.

Under **PEAK** test mode, press **POWE** button for power off. Under data reference mode, firstly press **POWER** button longer (over 3 seconds) for exit from data reference mode, returning to general test mode, then press **POWER** button for power off. During the exit from data reference, it will show "End" symbol.

#### 2. General Test

	High voltage, extremely dangerous! It must be operated by qualified staff that has acquired authority. The operator must strictly abide by the safety rules. Otherwise, there is electric injury danger, causing personal damage or casualty accident.
ł	Dangerous! It cannot be used to measure the circuit over 23KV voltage. Otherwise, there is electric injury danger, causing personal damage or equipment damage.
	Dangerous! It cannot be used to measure the circuit over 1000A voltage. Otherwise, there is electric injury danger, causing personal damage or equipment damage.

General Test: In the process of test, it will show the tested current value on real time by LCD display, and LCD data will vary with the current change. When the tester is removed away from the lead on test, it do not preserve the test result, LCD display will return to zero.


In general test mode, it is suitable for close distance measurement, convenient for circuit test by direct read of LCD data.

Before test, firstly to connect insulation rod, which must be connected in right position, and then to connect tester, avoiding the impact of meter to ground surface.
Make sure to use specially equipped insulation rod to connect with the meter.
After test, it should incline the insulation rod accordingly on drawing in. Firstly to tear down the tester and then the insulation rod, avoiding
the impact of meter to ground surface.

After normal boot, place the lead in the middle of clamp transducer domain, as shown in **Figure A**, with the meter transducer domain perpendicular to the lead, pushing the meter forwards to clamp the lead on test, showing the result on LCD display. If showing "OL A", it means the lead current

on test has exceeded the maximum volume on the level. Please select a higher gear level or a meter with greater measurement limit.

To pull backwards can make the meter remove from the lead on teat, as shown in **Figure C**, on removing, please try to keep the meter transducer domain perpendicular to the lead.



Under **HOLD** mode, press **HOLD** button to cancel HOLD function, and return to general test mode.

Under data reference mode, press **POWER** button longer (over 3 seconds) to exit from data reference mode, returning to general test mode.

Under **PEAK** test mode, press **POWER** button for exit from **PEAK** test mode, returning to general test mode.

After data deletion, it will return to general test mode automatically.



Attention! For the sake of safety, when test has been finished, please remove the meter away from the lead on test

#### 3. PEAK Test

PEAK test: the maximum current test. the meter will make automatic comparison on the changes in measured current, indicating the maximum value and maintain it, when the meter is removed away from the lead on test, the test result will be kept consistently, suitable for the circuit test on those LCD data hard to be read directly.

Under the general test mode, press **PEAK** button, **PEAK** 

indication light will be bright, enter into **PEAK** test mode. That means the meter will show and automatically keep the maximum value in the test.

Under any other mode, it must be returned to general test mode, and then make PEAK test according to the above operation.

Press **POWER** button to exit from PEAK test mode, returning to general test mode, and it will display "End" symbol during the exit.

#### 4. Data Maintenance

Under general test mode, press **HOLD** button to keep LCD display, "**HOLD**" symbol shows. Press **HOLD** button again for release of data lock, returning to general test mode, and "**HOLD**" symbol disappears.

#### 5. Data Memory

Under general test mode, press **HOLD** to storage data, at the same time, Meter will auto maticly form serial numbers, and memory the current preserved data. During the storage,

"**MEM**" symbol will show once by flash. This meter can memory 99 groups of data, in case of full storage, "**FULL**" symbol will show by flash continuously, and it cannot continue to memory until cleaning out the previous memory.

#### 6. Data Reference

Under general test mode, press **PEAK** + **POWER** button to enter data reference mode, showing "**MR**" symbol, meanwhile, it will automatically display data saved in the group 01. Then press **PEAK** or **POWER** button to read the stored data by turning upwards or downwards in cycle. It will return to the group 1's data automatically after reaching the last group's data in storage.

Press **HOLD** button to exit from data reference mode, returning to general test mode. During the exit, it will show "End" symbol.

#### 7. Data Deletion

Under data reference mode, press PEAK + POWER

button to delete all the data in storage, and return to general test mode. During the deletion of data, it will show "**dEL**" symbol.

#### **\*8.** Data Transmission

**B Type:** has the function of wireless data transmission. When the Meter under test mode, the test result will be transferred to receiver through wireless transmission, and the receiver will show test result on real time, being clear at a glance.

Only under test mode, the meter will transmit, If the receiver has not received emission signals, it will show "no - -" symbol dynamically.

#### B Type: Transferred

**VICTOR9000B Type:** Wireless transmission test data, a straight-line distance of about 30 meters, can penetrate the floor to receive data.

#### \*VICTOR9000B. Operation of Receiver

#### 1. Power On/Off

Press **POWER** to power on, LCD display, entre into data receive mode. If LCD show relatively dark after power on, it is possible that the battery & voltage is a bit lower. Please replace battery. In 15 minutes after power on of the receiver, LCD will continue flashing to give hint for being power off, after 30 minutes for continuous flash of LCD, it will shut down automatically, in order to lower the battery consumption. In case of LCD continuous flash, press **POWER** button, then the receiver will continue to work.

#### Under **HOLD** mode, press **POWER** to power off.

Under data reference, first, press **POWER** button( for 3 seconds ) to exit data reference mode, then come back to data receive mode, press **POWER** button once again to power off. During exit from data reference, it will show the symbol of **"End**".

#### 2. Data Reception

After normal power on, the receiver will under receiving mode. If there are emission data, the receiver will show the

test result on real time. If it has not received any signal, the receiver will search signals constantly, and show "**no**-"symbol dynamically.

#### 3. Data Maintenance

Under Data Reception mod, press **HOLD** button, keep LCD display, "**HOLD**" symbol indication. Press **HOLD** button once again to relieve data lock, return to data reception mode, "**HOLD**" symbol display.

#### 4. Data Memory

Under Date Reception mode, press **HOLD** button to maintain data, meanwhile, the receiver will automatically form serial numbers, and memory the current preserved data. During the storage, "**MEM**" symbol will show once by flash. This receiver can memory 99 groups of data, in case of full storage, "**FULL**" symbol will show by flash continuously, and it cannot continue to memory until cleaning out the previous memory.

#### 5. Data Reference

Under Data Reception mode, press **HOLD**+**POWER** button to enter into Data Reference mode, "**MR**" symbol display, meanwhile, it will automatically display data saved in the group 1. Then press **HOLD** button or **POWER** button to read the stored data by turning upwards or downwards in cycle. It will return to the group 1's data automatically after reaching the last group's data in storage.

Press **POWER** button longer (over 3 seconds) to exit from data reference mode, returning to receiving data mode. During the exit, it will show "**End**" symbol.


#### 6. Data Deletion


Under data reference mode, press **HOLD** + **POWER** button to delete all the data in storage, and return to Data Reception mode. During the deletion of data, it will show "**dEL**" symbol.

## VIII. Replacing Batteries

Warning! In case that the battery's cover board is not well closed, it is forbidden to make test. Otherwise, it is dangerous. Pay attention to the polarity of battery, in case of damage to the meter. Do not mix in the use of new and old batteries.

- When the battery voltage is below 4.8V, the meter will show " - + " symbol, indicating the batteries have no sufficient power content. Please replace batteries.
- 2. Power off, to make sure the meter is under the state of power off. To loosen two screws of the battery cover board, open the cover board to replace brand-new qualified batteries on. It should pay special attention on the battery specification and polarity, cover the board well and fasten the two screws.
- 3. Press **POWER** button to check whether the meter can be powered on normally. If not, please repeat the operation according the step 2.





# $\operatorname{I\!X}$ . Packing List

Tester	1PCS
*Receiver (ETCR 9000B special )	1PCS
Insulation Rod (1M/Section)	5 Sections
Meter Box	1PCS
Dettem: (Allieling Dm: Dettem: (AAA)	4 PCS (* or 8
Battery (Alkaline Dry Battery AAA)	PCS)
User's Manual/ Maintenance Card/ Conformity Certificate	1SET